Approved For Release 2002/06/18: CIA-RDP84-00951R000400010038-8 1 103 %

# COPY

12 July 1955

MEMORANDOM FOR: Executive, CD

SUBJECT: Demage to 350-26th Street Caused by the Heavy Rains of 8 and 9 July

The heavy rains of Fridey afternoon and Saturday, E and 9 July, resulted in a virtual flooding of several areas of 350-26th Street causing some damage and considerable inconvenience and interruption of operation. Areas of the building affected and damage incurred are as follows:

## AREAL

Northeast end of building.

Both restrooms and entrance area were covered with about
2 inches of water. The storm sewers were inadequate to
carry off the rain water which backed up through drain pipe
and plumbing (i.e. water fountain, toilets, etc.)

## DAMAGE

Actual damage was minimal. OCD staff blocked the flow of water with boxes of LIM cards to keep it from flowing into the working areas. Some 15,000 IBM cards were destroyed and the restrooms had to be closed.

## ARFA

Microfilm Laboratory (Resement NE end)
Approximately 2 inches of water backed up through supposedly
blocked off toilets covering about one-half of the basement
working area.

## DAMAGE

No actual damage resulted. However, all microfilm processing operations were suspended for the balance of the day as the staff had to be diverted to blocking and mopping the water.

## AFF.A:

Intellefer Card File Vault (East side of building)
On Friday afternoon a stopped up drain running through the
Vault from the roof backed up covering the floor with 2 inches

of water. All bottom file drawers had to be removed from some 40 card file cabinets. Legistics Office was notified at approximately 3:30 P.M.

Friday evening the drain backed up once again pouring water all over the floor. The water backed up high enough in the drain to cause it to over flow at the level of the vault ceiling thereby pouring water over all the card files in the south and of the vault and so weakening the ceiling that it fell down on top of the cabinets. Administrative Staff, OCD was notified at 11:30 P.M. by the Night Security Officer of the condition and staff of the Machine Division reported to the building and worked until 2:00 a.M. Saturday morning attempting to remove all cards which were not already ruined and which were likely to be water scaked and sweeping out the water.

Public Building Service personnel attempted to clean the clogged drain and by 2:00 A.M. Saturday assured OCD personnel that the situation was remedied and the drain cleared.

Again on Saturday noming the heavy rain backed up the drain causing a minor flooded condition.

## DAMAGE

Approximately 50% of the vault area and parts of the heavy machine room and card punch room were under water. Fortions of 100 IBM card trops holding 300,000 numbed intellofex cards were soaked. It's impossible at this time to estimate how many of these cards are completely unusable. Every effort is being made to dry the cards by using fans, de-humidifiers, etc. Reproduction of such cards will be costly and time consuming.

25X1A9a
Acting Chief, Machine Division